
IN THE CITY OF SAINT PAUL, HOWARD COUNTY, NEBRASKA FINAL PLAT



F: \projects\010-1269_SVYO\Final_Plat\0101269_FP-Lukasiew Aug 09, 2010 2:17pm XREFS: 0101269_xbase

CENTER

SEC. 34-T15N-R10W

SECTION TIES

NORTH 1/4 CORNER. SEC. 34-T15N-R10W
FOUND CAR VALVE IN ASPHALT
W 60.63' TO 'X' ON TOP OF ROW MARKER
NE 89.60' TO 'X' ON TOP OF ROW MARKER
E 79.52' TO 'X' ON TOP OF ROW MARKER
E 10.00' TO CENTER LINE OF HIGHWAY 281

E 80.00' TO 5/8" REBAR


CENTER. SEC. 34-T15N-R10W
FOUND NDOR BRASS CAP ±0.3' BELOW GRADE
E 29.50' TO CENTER LINE OF HIGHWAY 281
WNW 4.24' TO 1-1/2" PIPE (DEARMONT CORNER)
WSW 36.48' TO PK NAIL IN FENCE POST
WNW 43.84' TO PK NAIL IN POWER POLE

SOUTH 1/4 CORNER, SEC. 34-T15N-R10W FOUND 1/2" PIPE ±0.4' BELOW GRADE NE 75.65' TO 5/8" REBAR E 67.60' TO 5/8" REBAR NNW 38.90' TO PK NAIL IN POWER POLE SSW 42.34' TO PK NAIL IN POWER POLE SW 25.92' TO CENTER OF MANHOLE

NORTH 1/16 CORNER, NORTHEAST 1/4, SEC. 34-T15N-R10W FOUND 5/8" REBAR W/CAP

E 7.61' TO PK NAIL w/WASHER IN CORNER FENCE POST
E 0.97' TO PK NAIL w/WASHER IN BRACE POST
W 19.35' TO PK NAIL w/WASHER IN FENCE POST
N 19.50' TO CENTER LINE OF EAST—WEST COUNTY ROAD

SEC. 34, TI5N, R10W NOT TO SCALE



SURVEY RECORD REPOSITORY
RECEIVED

OCT 2 8 2010

5 5
County Howard

990-343 1/2

OWNERS: DON LUKASIEWICZ AND DEETTE LUKASIEWICZ SUBDIVIDER: DON LUKASIEWICZ AND DEETTE LUKASIEWICZ SURVEYOR: OLSSON ASSOCIATES ENGINEER: OLSSON ASSOCIATES

NUMBER OF LOTS: 1

SHEET 1 OF 2



201 East 2nd Street P.O. Box 1072 Grand Island, NE 68802-1072 TEL 308.384.8750

DON & DEETTE
LUKASIEWICZ SURVEY
FB HOWARD CO. #5